

# Product Warehouse Inspection



<b>Product:</b>	Freezer
<b>Goodada ID#:</b>	1228
<b>P/O Number:</b>	N/A
<b>Client Name:</b>	Beckford Industries Limited
<b>Warehouse Name:</b>	JPI Warehousing (SOTON) Limited
<b>Inspector Name:</b>	Aidan Conaty
<b>Location:</b>	Eastleigh United Kingdom
<b>Inspection Date:</b>	6 <sup>th</sup> June 2018

## 1.0 Inspection Description

<div style="text-align: center;">  <p><b>Ice Point Freezer</b></p> </div> <div style="text-align: center; margin-top: 20px;">  <p><b>Freezer &amp; Freezer Carton</b></p> </div>	<b>Product:</b>	Freezer
	<b>Goodada ID#:</b>	1228
	<b>P/O Number:</b>	N/A
	<b>Client Name:</b>	Beckford Industries Limited
	<b>Warehouse Name:</b>	JPI Warehousing (SOTON) Limited
	<b>Inspector Name:</b>	Aidan Conaty
	<b>Location:</b>	Eastleigh United Kingdom
	<b>Inspection Date:</b>	6 <sup>th</sup> June 2018
	<b>Expected Order Quantity:</b>	236
	<b>Quantity Counted:</b>	234
<b>Products Opened:</b>	2	

## Important Remarks / General Defects

### Client Requirement:

1. There should be 236 freezers stored at this warehouse. Check the following:  
Total quantity, condition of goods & packing, and if possible check the working condition



### Report Findings

1. There are only 234 freezers in stock at this warehouse.
2. The products are stored eight to a pallet in each row holding four freezers.
3. There are service cartons which are damaged.

### Inspector Remarks

- Alan Guertin and Dan from JTI were very helpful.
- Dan drove the forklift and moved all the pallets so that I could visually count and record all the freezers.
- There are some washing machines in storage at this warehouse.
- I opened two freezers and switched them on for testing. Visually they appear to work fine.

**Table 1-Inspection Findings**

Inspection Details	
<b>Inspector</b>	 <b>Aidan Conaty</b>
<b>Inspector at Location</b>	 <b>Aidan Conaty at JPI warehouse in Eastleigh</b>
<b>Number of Inspection Days:</b>	1 day
<b>Arrival Time</b>	10.30am
<b>Completion Time</b>	12.30pm

Inspection Date: 06/06/2018

“Promote your Product on Goodada”

### Inspection Standards

<b>Sampling standard:</b>	ISO 2859-1 (Mil Std 105E)
<b>Total number of products:</b>	234
<b>Number of inspected components:</b>	2
<b>Total number of cartons</b>	234
<b>Number of inspected cartons:</b>	234

### Inspection Location

<b>Inspection location:</b>	Eastleigh United Kingdom
-----------------------------	--------------------------



**Eastleigh United Kingdom**

**2.0 Stored Quantity**

**Quantity Table**

Expected Result	Result	Actual Finding / Comments
236	<b>FAIL</b>	234

**Photos of Order Quantity**

 <p><b>Figure 1</b></p>	 <p><b>Figure 2</b></p>
--	---

**3.0 Packing**

**Packing Request**

Expected Result	Result	Actual Findings/ Comments
Review Packing	<b>Client Confirmation</b>	There were four damaged boxes. The cartons were very dusty on the top of the pallet.



Photos of Packing



Damaged Carton 1



Compressed Carton



Damaged Carton 2



Cartons & Pallets being counted

**4.0 Shipping Mark**  
**Shipping Mark Request**

**Photos of Shipping Marks & Logos**



**Cleared Label**



**Label showing Date**



**Barcode of Product**



## 5.0 Counting Process



Initial 8 pallets with 8 products per pallet



16 pallets (note two units randomly chosen for visual inspection)



14 pallets (note two pallets only have 4 units per pallet)



1 pallet only holding two units

## 6.0 Freezer Testing



## Additional Photos



**Freezers stored in Warehouse when I arrived**



**Side view of Freezers stored in Warehouse**



**Freezers stored and wrapped on Pallets**



**Front of Freezer Box**



**Accessories inside Freezer**



**Dan driving Forklift and moving Freezers for count**

## *END OF REPORT*

Disclaimer Note:

1. This report reflects our findings at the time and the place of inspection based on random samples selected.
2. This inspection was carried out to the best of our knowledge and abilities, and our responsibility is limited to the exercise of reasonable one.
3. This report does not relieve the sellers from their contractual obligations nor does it prejudice buyer’s right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter.
4. Our services are subject to the General Conditions of Service of Goodada Inspections, which is shown at our website and can be sent to you upon written request.
5. We only conduct visual inspections on the products. Our inspections cover sections within this report.
6. For inspections in all other areas the buyer should have the product sent to an appropriate testing facility.
7. If inspection result is a “Fail” this constitutes all other parts of product are a “Fail”.



# Quality Control Inspection Reports



*“It’s always better to find a fault at the factory floor and not  
at your door”*